

United States Government

Department of Energy

Rocky Flats Office

Memorandum

DATE 7-27-90
ACTION J. Evered

JUL 10 1990



000025460

ERD:SRG:7060

Relocation of the Marker for Surface Water Sampling Station SW-61

Jack Kersh, Associate General Manager
Environmental Restoration & Waste Management
EG&G Rocky Flats, Inc.

It has come to our attention that the sign for Surface Water (SW) sampling station SW-61 in South Walnut Creek has been moved. SW-61 historically has been at the location of the concrete culvert from the Perimeter Security Zone (PSZ), just north of SW-60, located at the metal culvert from the PSZ. The current location of SW-61 is downstream from it's historical point, where the flow from two other sampling points are combined (SW-59 and SW-60). This brings into question the data from SW-61 since the sign for this sampling location has been moved. Therefore, an investigation of this matter is in order.

In addition, my staff noted that there is no location marker for SW-21, also in South Walnut Creek, at the V-notch weir adjacent to the sewage treatment plant. This sampling location is supposed to monitor the combined flows from SW-59, SW-60, and SW-61. A location sign should be placed at this location.

You are requested to respond in writing with the results of your investigation within ten days after receipt of this memorandum.

If you have any questions please contact Scott Grace of my staff at 966-7199.

David P. Simonson
David P. Simonson, Acting Assistant Manager
for Environmental Management

CC:
R. M. Nelson, Jr., DOE/RFO
M. Van Der Puy, DOE/RFO
B. P. Warner, EG&G/RF
J. Evered, EG&G/RF
T. Greengard, EG&G/RF
M. Arndt, EG&G/RF

Received for Addressee
Corres. Control RFP

05 JUL 11 11 30 AM '90
CORRESPONDENCE CONTROL
ROCKY FLATS PLANT

ADMIN RECCRD